

ARCHITECTURAL ADVISORY COMMITTEE

DATE:	1	November 10, 2020	NOV 12 2020				
APPLICANT:		5 Danbury Road	DI ANNING & ZONING				
		Play a Part LLC	COMMISSION				
MEETING LOCATION AAC MEMBERS: (Place check next to tho	Back Lowe	Annex er Level Conference R	RIDGEFIELD, CT AAC/VDC OMApproved Date: //////20 Signature Note:				
Enderstone Enderstone	J. Clements	☑J. Goldfluss	J. Heyman				
I. Kinnear I. I. Kinnear I. I	☑L. Lavelle	☐G. Lounsbury					
ALSO PRESENT:		Ms. Hanlon					
APPLICATION: ACTION:	Special Permit − New Building Special Permit − Addition Sign Exterior Renovation AAC recommends design approval as noted AAC does not recommend design approval Additional design studies/information requested Other:						
COMMENTS, EXCEPTIONS AND/OR RECOMMENDED CONDITIONS							
The AAC recommends approval of the sign submitted with the following recommendations:							
 The sign should be 1½" thick with the green color wrapping around the edges. The Town Building Inspector should check the existing wiring of the sign lights on the pole and building. Overhead wires instead of underground cables are installed. 							
Vote For approval of recommendations: 4 Against approval of recommendations: 0							

BY: John Kinnear



ARCHITECTURAL ADVISORY COMMITTEE

TO BE WELL SHOW THE PROPERTY OF THE PARTY OF		And the second of the second o	CHEST CONTRACTOR OF THE PARTY O				
DATE:		November 10, 2020					
APPLICANT:		108 Danbury Road		RECEIVED			
		Chase		NOV 12 2020			
MEETING LOCATIO		Town Hall Annex Back Lower Level Conference Re		PLANNING & ZONING COMMISSION			
AAC MEMBERS: (Place check next to those S. Benton S. Kinnear S. ALSO PRESENT:		☑J. Goldfluss ☑G. Lounsbury Mr. O'Connor.	□J. Hey	yman			
APPLICATION:	☐ Special Permit – New Building ☐ Special Permit – Addition ☐ Exterior Renovation		☐Site Plan Approval Sign ☐Other:				
	□ AAC recommends design approval as noted □ AAC does not recommend design approval □ Additional design studies/information requested □ Other:						
COMMENTS, EXCEPTIONS AND/OR RECOMMENDED CONDITIONS							
The AAC does not recommend a second sign of equal size to the sign facing Danbury Road, to be located on the north side of the building. The bank has a freestanding sign that provides identification from both directions on Danbury Road already.							
For clarification, two signs are permitted with the approval of the Planning & Zoning Commission, but the AAC does not recommend this additional sign.							
Vote For approval of recommendations: 4 Against approval of recommendations: 0							

BY: John Kinnear