

Rail trail bridge

Daniel Donovan



Everyone loves before and after pics.








Why is the cost different?

- There was an increase in material needed
- The change in dimensions for my "framing" caused a large change in cost per unit
- The building of a railing created the need for timber locks



The new order cost: \$940.01

Line Product Code Total 2X10X16 TREATED SYP #1 179.94 29.99 ea 2 PT540616 5/4X6X16 TREATED SYP PREMIUM 202.41 22.49 ea WE DO NOT OUT DESCRIBE TREATED LUMBER 17920 10.99 SCORPION 2-1/2" XT2 CERAMIC COATED SCREW 19.99 19.99 SCOPPION 3º YT2 CERAMIC COATED SCREW 111 10.99 21 08 "1" RIBBED SCREWS (SHINGLE NAILS)" - NEED 1 LB 1 3/4" GALV SHAKE NAIL 134HGSK 4.99 OUR STOCK SHAKE NAIL IS RING SHANK Total Amount

The old order cost: \$468.26